

FIG. 1  
PRIOR ART





FIG. 2  
PRIOR ART



10064350 000000

FIG. 3




FIG. 4A




FIG. 4B




FIG. 4C







FIG. 4D




# FIG. 5A



# FIG. 5B



# FIG. 6A



# FIG. 6B




FIG. 7




FIG. 8




FIG. 9




FIG. 10





FIG. 11



MEASURING CONDITION

REFERENCE: WHITE REFLECTOR,  $\theta = 0$ , SLIT: 0.2, ND FILTER: NONE  
 SAMPLES:  $\theta = 0 \sim 60^\circ$ , SLIT: 0.2, ND FILTER: ATTACHED (ND = 3)



FIG. 12A




FIG. 12B




FIG. 12C




FIG. 12D




FIG. 13




FIG. 14A





FIG. 14B



200200 05542001

FIG. 15A




FIG. 15B




FIG. 16




FIG. 17

